Oil Field Environmental Incident Summary

Responsible Party: Republic EES, LLC
Well Operator: TERVITA, LLC

Well Name: Alexander Treating Plant #1

Field Name: ELK

Well File #:

Facility ID #: 700025-01
County: MCKENZIE

Twp Rng Sec Qtr: 152 101 18 E/SW

Location Description: Produced water spill occurred at the Alexander TRD and less than half mile

along adjacent public road.

Submitted By: Jerry Beckman

Received By:

Contact Info: Thomas Johnson

PO BOX 2301

WATFORD CITY ND 58854

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Other

Release Contained: Yes - On Facility Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 20 Gallons

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd:

Risk Evaluation:

Very low risk

Areal Extent:

Potential Env. Impacts:

The only impacts were to surface soil. Due to the low quantity that was released impacts were very minor.

Action Taken/Planned:

It is instructed that all drivers complete a detailed pre-trip walk around before driving off the site to prevent such incidents. Action regarding this specific incident is being internally addressed.

Wastes Disposal Location:

Clean up of the spill occurred immediately after discovery. Waste recovered will be incorporated into the TRD.

Other Agencies Involved:

Updates

Date: 8/14/2019 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update